YAMAHA

Yamaha CS-700
Firmware Version: 1.4.1.11
Product Release Notes
December 28, 2020

New features and improvements in this firmware release:

Summary	Notes
CS-700 USB Audio device re-enumerates	Implemented scheme to force Windows to re-enumerate the CS-700 Audio devices
Provisioning server	The provision server configuration will accept fully qualified domain names and resolve them to an IPv4 address

Issues resolved in this firmware release:

Summary	Notes
Room control password not persistent	The room control password would reset to its default value when the CS-700 restarted.
Dialer App crash	The Dialer App would crash when a SIP call connected.
Bluetooth PIN not always reset correctly	The Bluetooth PIN may not reset correctly on a "reset to factory defaults" request.
Zoom mic mute synchronization (Mac OS only)	Updated UAC telephony HID report.
The IP dialer app could not send '*' or '#' from the keypad.	The correct DTMF tones weren't sent when the IP dialer app used '*' or '#'.