



Sep, 2018
YAMAHA Corporation

Important notice

In VXL1-16P installed Dante firmware 4.0.8.19-4.0.8.4-1.0.0, if the Dante devices in the network link-up together*, there are cases in which noise is emitted from the VXL1-16P for several seconds. To prevent the occurrence of noise, Please update to the latest Dante firmware. For instructions on updating firmware, please refer to the Audinate Dante Firmware Update Manager User Guide.

* Such as when the power supplies of the switches are turned on simultaneously

重要なお知らせ

Dante firmware 4.0.8.19-4.0.8.4-1.0.0がインストールされたVXL1-16Pにおいて、ネットワーク内のDante機器が一斉にリンクアップされた場合*、VXL1-16P から数秒間ノイズが出る場合があります。ノイズの発生を防ぐため最新のDante firmwareにアップデートいただきますようお願いいたします。Firmwareの更新方法はAudinate Dante Firmware Update Managerユーザーガイドをご覧ください。

*スイッチの電源を同時にいっせいにON する等