

Previous 01V96i Firmware **version information**

V1.02 for Mac

New Features

- Now supports macOS 10.14.

Fixed bugs

- Solved a problem in which MIDI NRPN control commands could not be received.
- Solved a problem in which it had been impossible to select SINGLE mode when transmitting and receiving signals of a high sampling rate (88.2 kHz/96 kHz) via the ADAT connector.